

ACURA DOOR LOCKS

General information as follows:

1. Key blank references are for the profile only, using one of the more well-known blank numbers. This list does not include all variations of different head shapes, lengths, or transponders, the main object is to identify which key profile enters the lock.
2. Identify which tumblers and keying kits to use according to the separate chart organized by the key blank numbers.
3. Note the following terminology:

“Lock Service Package” may come coded or uncoded and includes a face cap when applicable. In some cases a coded lock may be substituted for applications listed as uncoded, but an uncoded lock will never be substituted for an application listed as coded. The original pawl may need to be reused on some applications. A pawl may be included with the lock but it may not be the correct one for every application.

“Complete Lock” is a coded lock including the correct pawl for the listed application.

Items marked DWO are discontinued when out. The part numbers are listed for the benefit of those who already have stock.

IMPORTANT: RIGHT SIDE (RH) is the PASSENGER SIDE, LEFT SIDE (LH) is the DRIVER SIDE. If only one part number is listed, that part number can be used on either side.

Model	Years	Key	Part description	Part no.	Part description	Part no.	Notes	
CL	1997-99	HD103	Complete lock RH	D-19-112	Complete lock LH	D-19-113		
CL	2001-03	HD103	Complete lock RH	D-19-120	Complete lock LH	D-19-121		
CSX (Canada)	2006-11	HO03	Complete lock RH & LH	D-19-131				
EL (Canada)	1996-00	HD103	Lock service package including pawl RH	D-19-210	Lock service package including pawl LH	D-19-211		
EL (Canada)	2001-02	HD103	Complete lock RH	D-19-120	Complete lock LH	D-19-121		
EL (Canada)	2003-05	HO03	Complete lock RH	D-19-124	Complete lock LH	D-19-125		
Integra	1986-89	X181	Uncoded service pack including pawl RH	D-19-208	Uncoded service pack including pawl LH	D-19-209	Use face cap P-19-211 (on handle)	
Integra	1990-93	HD103	Complete lock RH	D-19-111	Complete lock LH	D-19-110		
Integra	1994-01	HD103	Complete lock RH Without correct pawl for this model	D-19-112	Complete lock LH without correct pawl for this model	D-19-113	The correct pawls are available separately as follows: P-19-311 for right side P-19-312 for left side	
			Complete lock RH Includes pawl	D-19-212	Complete lock LH Includes pawl	D-19-213		
Legend standard trim	1986-90	X181	Uncoded service pack including pawl RH plug length 1.38 inch	D-19-201	Uncoded service pack including pawl LH plug length 1.38 inch	D-19-202	Use face caps (on handle) without lighted keyhole: P-19-216 with lighted keyhole: P-19-219	
Legend L & LS trim level	1986-90	X181	Uncoded service pack including pawl RH plug length 1.46 inch	D-19-208	Uncoded service pack including pawl LH plug length 1.46 inch	D-19-209	Use face caps (on handle) without lighted keyhole: P-19-216 with lighted keyhole: P-19-219	
Legend coupe	1991-95	X181	Replacement locks are available from Acura dealers only					
Legend sedan	1991-95	X181	Replacement locks are available from Acura dealers only. Face caps to service original locks: without lighted keyhole: P-19-212, with lighted keyhole: P-19-213					
MDX	2000-06	HD103	Complete lock RH	D-19-120	Complete lock LH	D-19-121		
MDX	2007-13	HO03	Complete lock RH & LH	D-19-131				
NSX	1991-05	HD103	Uncoded service pack including pawl RH	D-19-204 (DWO)	Uncoded service pack including pawl LH	D-19-205 (DWO)		

Scroll down for more



TEXTING WHATSAPP:

+1 (213) 310 3334

TOLL FREE:

+1 (844) 539-4462

SALES@KEY4.COM

WWW.KEY4.COM

ACURA DOOR LOCKS

RL	1996-04	HD103	Uncoded service pack including pawl RH	D-19-206	Uncoded service pack including pawl LH	D-19-207	
RL	2005-07	HD103	Replacement locks are available from Acura dealers only.				
RDX	2007-08	HO03	Replacement locks are available from Acura dealers only.				
RLX	2014-17	HO03	Replacement locks are available from Acura dealers only.				
RSX	2002-06	HD103	Complete lock RH	D-19-120	Complete lock LH	D-19-121	
SLX	1996-99	X184	Complete lock RH	D-24-105 (DWO)	Complete lock LH	D-24-106	
TL	1995-98	HD103	Replacement locks are available from Acura dealers only.				
TL	1999-03	HD103	Complete lock RH	D-19-120	Complete lock LH	D-19-121	
TL	2004-06	HD103	Replacement locks are available from Acura dealers only.				
TL	2007-08	HO03	Replacement locks are available from Acura dealers only.				
TL	2009-14	HO03	No lock on RH side		Complete lock LH	D-19-135	
TSX	2004-08	HD103	Replacement locks are available from Acura dealers only.				
TSX	2009-14	HO03	Complete lock RH	No lock	Complete lock LH	D-19-135	
Vigor	1992-94	HD103	Complete lock RH	D-19-111	Complete lock LH	D-19-110	

Which tumblers and keying kits to use:

The chart below lists which tumblers and keying kits to use according to which key blank the lock uses. Some of these parts are no longer available for new purchase but are listed for the benefit of those who already have them (marked DWO / Discontinued When Out).

Key Blank	#1 depth tumbler	#2 depth tumbler	#3 depth tumbler	#4 depth tumbler	#5 depth tumbler	#6 depth tumbler	Keying kits and Notes
HD103	P-19-141	P-19-142	P-19-143	P-19-144	P-19-145	P-19-146	A-19-104 keying kit containing this series only A-19-100 combination kit containing this and other series, no longer available for new purchase (DWO)
HO03	P-19-161 (split)	P-19-162 (split)	P-19-163 (split)	P-19-164 (split)	P-19-165 (split)	P-19-166 (split)	A-19-108 keying kit containing P-19-161/166, plus full size supplemental wafers P-19-160, P-19-167, P-19-168, and P-19-169. Locks contain only one full size supplemental wafer, determine use by comparing to pictures on the kit layout card.
	P-19-167 (full size)	P-19-168 (full size)	P-19-169 (full size)	P-19-160 (full size)			
X181	P-19-111	P-19-112	P-19-113				A-19-101 keying kit containing this series only A-19-100 combination kit containing this and other series, no longer available for new purchase (DWO)
X184	P-30-161	P-30-162	P-30-163	P-30-164			A-30-106 keying kit containing this series only A-30-150 combination kit containing this and other series, no longer available for new purchase (DWO)

Tumbler springs:

Over the years we have sold tumbler springs under several different part numbers. As there are very minor differences between the springs used in most Japanese and Korean locks, we have consolidated the various springs as follows:

P-00-100 - currently active part number - 100 springs per pack

Part numbers previously used, now superseded to P-00-100

P-16-105	P-30-108
P-19-100	RP6546
P-20-105	RP6612
P-20-115	RP6731
P-24-105	RP6822
P-30-105	



TEXTING WHATSAPP:

+1 (213) 310 3334

TOLL FREE:

+1 (844) 539-4462

SALES@KEY4.COM

WWW.KEY4.COM